## BHARAT COKING COAL LIMITED

(A Subsidiary of Coal India Limited)
Office of the General Manager:Barora Area
Excavation Department
P.O. Nawagarh,Dist.DHANBAD-828306

Ref no: CGM/BA/AM(Excvn)/NIT/10-11/ 5520 Dated: 07.01.2011

## **NOTICE INVITING TENDER**

Sealed tenders are invited in 2 bid system (Techno-commercial & price bid) from experienced contractors/repairers for undertaking the following repair job of Barora Area, BCCL

Sl	Description of	Estimated	Earnest	Last date	Date &	Work	Minimum
no	job	value of	money	& time	time of	completion	Warranty/
		tender (Rs.)	(1% of estimated value)	for submissio n of	opening of tender	period	Guarantee
			(Rs.)	tender			
1.	Repairing / replacement of Front end Assy.and Hoist Machinary of BE- 195 (10 M³)Shovel, Sl.No.140763, BCCL No.S-87 of Muraidih OCP.	2,31,000=00	2310=00	04.02.11 up to 1.00 p.m.	04.02.11 at 3.30 p.m.	15 days from issue of work order or handing over of job for repair whichever is later	2000 hrs or 12 months from the date of completion & handing over of the work whichever is later.

Tender paper & Tender document will be issued from 28.01.11 to 03.02.11 during office hours from the Office of the Area Manager (Excvn), Barora Area, BCCL upon submission of DD for Rs.250.00(Rs Two hundred Fifty only) payable to Bharat Coking Coal Limited payable at Dhanbad or by deposition of cash at Cash Section of Barora Area. The rest of the details like terms & conditions are in the Tender Document. Sealed tenders are to be submitted in the tender box placed in the Office of the Area Manager (Excvn), Barora Area. Tenderers must submit their Bank A/c. details in prescribed format which will be issued alongwith tender document. Failure to submit the same by the bidder, his offer may be liable to be rejected. The sale of tenders shall be stopped one day prior to the last day of submission of tender. The tenderers may inspect the item for repair at Muraidih OCP on any working day during working hours prior to submission of tenders.

## **SCOPE OF WORK:**

- A. <u>Dismantling of</u> (1) Crowd cushion Assly.(2) Dipper Handle. (3) Upper Boom support pin. (4) Pendant Assly.-1 No. (5) Lower Boom support LHS. (6) Lower Boom support RHS. (7) Boom Bumper Assly & foundation. (8) Lower Boom Hinge pin. (9) Saddle Assly with both side sheave and shaft. (10) Dismantling / Lowering of Lower Boom Assly.(11) Retract rope guide sheave Assly (12) Retract rope guide sheave Assly foundation. (13) Dipper Trip mechanism with motor & foundation. (14) All other accessories with auto lub injectors with foundation, Trip rope guide sheave Assly with foundation etc. (15) Worn out hoist gear (inter) Assly with both side block. (16) Both end bearing of inter pinion shaft.
- (17) Gear from inter pinion shaft.
- B. Repairing of (1) Lower Boom foundation. (2) Lower Boom Hinge pin with lock. (3) Lower Boom support hinge.
  (4) Lower Boom support hinge pin with lock. (5) 'A' frame Pendant hinge.
- C. Assembling of (1) Lower Boom hinges. (2) Lower Boom with support & saddle Assly.(3) Saddle Block Assly with saddle sheave. (4) Retract rope guide sheave with foundation and alignment. (5) Dipper Trip mechanism with foundation and alignment. (6) Both side Bumper Assly with foundation and alignment. (7) Upper Boom Assly.
- (8) Upper Boom support. (9) Serviceable gear (after dismantling of inter pinion shaft) with new shaft.
- **D.** Repairing / Assembling of Hoist inter gear Assly. **F.** Commissioning / Testing.

Note: Job has to be done at site (Muraidih OCP) and only electric supply will be provided by BCCL.

Area Manager (Excvn) Barora Area, BCCL

## Copy to:

- (1) GM / AGM / AFM, Barora Area. (2) G.M.(Excvn), Koyla Bhawan.
- (3) G.M.(System), Koyla Bhawan—For publication of tender on web site as per laid down procedure.
- (4) Public Relation Officer, BCCL, Koyla Bhawan. (5) Notice Board-Barora Area