BHARAT COKING OOAL LIMITED (A SUBSIDIARY OF COAL INDIA LIMITED) OFFICE OF THE CHIEF GENERAL MANAGER BLOCK-II AREA, PO- NAWAGARH, DIST- DHANBAD

1933

following repair job of Block-II Area of BCCL-

Si	Description of job	Estimated value (Rs)	Earnest money (Rs)	Last date of receipt of tender	Date of opening of tender	Cost of tender docu- ment	Job Completi on period	Warranty
	Repairing of dipper stick assy taken out from P&H98 shovel of BOCP.	Rs 228024/-	1% Earnest money	28.7.09 by 100 P.M.	28.7.09 st 3.00 P.M.	100=00	20 days	2000 w/hr or 12 months from the date of commissioning which-ever comes earlier.

Issue of tender document- up to 19.7.09 to 24.7.09

(On all working days during working period except on Sunday/Holiday)

1) Eligibility -The tenderer must have experience of successfully completed similar work during last seven years ending last day of the month previous to the one in which tenders are invited should be any one of the following-

i)Three similar completed works each costing not less than the amount equal to 40% of the estimated cost.

ii)Two similar completed works each costing not less than the amount equal to 50% of estimated cost. iii)One similar completed work costing not less than the amount equal to 80% of the estimated cost.

2) Average annual financial turn over during last three years ending 31st March of the previous

financial year should be at least 30% of the estimated cost.

3) Security deposit and performance guarantee- 10% (including earnest money) of work order amount to be deposited within 10 days of issue of work order by qualified tenderer. The earnest money will be retained as security money the qualified tenderer will have to deposit additional amount. After completion of work ,this amount will be retained as performance guarantee which will be released after satisfactory completion of guarantee period

4)The tenderer must have valid sale tax registration/VAT/TIN, service tax registration and latest copy of income tax return

filed along with PAN

5) Payment - 100% payment will be made after satisfactory completion of work on submission of bill

6) Safety precaution should be taken by the repairer. Safety aspect will be the sole responsibility of the repairer. The contractor persons must be trained at VTC and their names/attendances must be marked in form 'B/D/E 'before engaging them in mines

The details of job, terms and conditions will be available in tender documents.

- 8)The tender documents can be had from the office of Area Manager (Excv) ,Block-II Area on submission of cash of requisite amount to Area Finance Manager Block-II Area or demand draft /banker's cheque of requisite amount in favour of 'Bharat Coking Coal Limited ' payable at Dhanbad issued from any nationalized bank. It can be downloaded from website of BCCL.
- 9) The tenders will be received up to 1.00P M.on the scheduled date and will be opened at 3.00P.M.on the same date.
- 10) Tenderers may submit their offer for one or more job but they are required to submit separate set of offer for each job

11) The term similar work stands for HEMM repairing involving reconditioning.

Area Manager (Excy Block-II Area , BCCL

CC-1)GM/AGM/AFM Block-II Area

2)Notice Board-All Areas

3) Notice Board -Block-II Area

4)CGM(Excy.)/Koyla. Bharan.

5)PRO/Koyla Bhavan-along with i)5 copies of tender notice for wide publication on website and news paper ii)2 copies of tender document for placing on web site.

