#### BHARAT COKING COAL LIMITED

(A Subsidiary of Coal India Limited)
Office of the General Manager
Block-II Area: P.O. Nawagarh
DHANBAD

Ref no: GM/BII/Excvn/NIT/10/058/1699 Dated: 25/08/10

### **NOTICE INVITING TENDER**

Sealed tenders are invited from reputed electrode manufacturers/their authorized dealers or authorised reclaimers in 2 bid system (Techno-commercial & price bid) for undertaking the following repair job of Block-II Area, BCCL

Sl	<b>Description</b> of	Estimated	Earnest	Last date	Date &	Work	Minimum
no	job	value of	money(2%	& time for	time of	completion	Warranty/
		tender	of	submission	opening	period	Guarantee
			estimated	of tender	of		
			value)		tender		
	Repairing of	413400.00	8268.00	17.09.10	17.09.10	30 days of	2500 hrs or 12
1.	bucket assy of			up to 1.00	at 3.30	issue of work	months from the
	P&H 1900AL			p.m,	p.m.	order/handing	date of
	shovel, SL no 88					over of job for	completion &
	of BOCP (The					repair	handing over of
	work also					whichever is	the repaired
	includes fitting of					later	work whichever
	new front wall						earlier.
	assy).						

Tender paper & Tender document will be issued from 02.09.10 to 16.09.10 during office hours from the Office of the Area Manager (Excvn), Block-II Area, BCCL upon submission of DD for Rs.250.00 (Rs two hundred fifty only) payable to Bharat Coking Coal Limited payable at Dhanbad. The rest of the details like terms & conditions are in the Tender Document. The tender documents to be submitted in the tender box placed in the Office of the Area Manager (Excvn)), Block-II Area. The sale of tenders shall be stopped one day prior to the last day of submission of tender. The tenderers may inspect the item for repair at BOCP on any working day during working hours prior to submission of tenders SCOPE OF WORK

- 1. Cutting/Removal of old dipper front from the bucket & making 'V' grooves on the to be joined portions of the bucket & the new front wall.Grinding & finishing of the 'V grooves for joining.
- 2. Fitting, aligning & joining of the new dipper front(supplied by BCCL) with the bucket. Complete welding/joining of the of the dipper front with the bucket with suitable jointing electrodes.
- 3. Repairing of major cracks in the top wall of the bucket & repairing of the other cracks on the rest of the bucket.
- 4. Welding of stiffners with suitable electrodes for strengthening.
- 5. Repair of the bucket door assy including repair of cracks, repair of the door edges, repair of the brackets, stiffner welding for strengthening & hardfacing with suitable electrodes.
- 6. Removal of worn out bushings & repair of the bushing housings & fitment of the new bushings (provided by BCCL).
- 7. Hardfacing of the new dipper front wall with suitable electrodes.

Area Manager (Excvn) Block-II Area, BCCL

#### CC:

- 1. General Manager, Block-II Area
- 2. Notice Boards: Barora, Block-II, Govindpur,Katras, Sijua,Kusunda, Putki-Balihari, Kustore,Bastacola,Lodna, Eastern Jharia,Chanch Victoria, Western Jharia, & other Areas of BCCL
- 3. Notice Board, Block-II OCP, Jamunia OCP, RRWS
- 4. The Sr Systems Office, BCCL to upload the tender in Website & publish in newspapers.

## BHARAT COKING COAL LIMITED



(A Subsidiary of Coal India Limited) Office of the Chief General Manager Block-II Area: P.O. Nawagarh DHANBAD

Ref no: GM/BII/Excvn/NIT/10/058/1699

# TENDER DOCUMENT

- 1. ELIGIBILITY: The tenderer must have experience of SIMILAR work during last seven years ending last day of previous year to the one in which tenders are invited as any one of the following
  - a. Three similar completed works each not less than 40% of the estimated value of the tender.
  - b. Two similar completed work each not less than 50% of estimated value of the tender.
  - c. One similar completed work not less than the amount equal to 80% of the estimated value of the tender.

Dated: 25/08/10

SIMILAR works means any repair/reclamation work of HEMM involving welding, rebuilding, grinding, machining, etc whichever is applicable.

- 2. The average annual financial turn over during the last 3 financial years ending 31st March should be at least 30% of the estimated value.
- 3. The tenderers must submit copy of valid Sales Tax registration, VAT/CST registration, TIN registration, Service Tax registration along with copy of PAN of the firm/proprietor. The submitted documents should be attested by a NOTARY.
  - The tenderer shall be barred from taking part in the future tender, if any documents/information submitted by the tenderer is found to be incorrect/false.
- **4.** WARRANTY: If any item repaired against the work order fails because of poor workmanship or quality, the same shall be replaced/repaired free of cost within 15 days failing which the LD clause as in sl no 9 will be applicable & the company shall have the power to recover the total repairing cost of the failed items from any of the pending bills of the repairer.
- 5. PAYMENT: 100% payment will be made within 30 days of submission of bill after completion & acceptance of job.
- **6. SECURITY DEPOSIT:** 10% of the total value of the work order shall be deposited by the repairer in the form of Bank Draft before starting the job. Earnest money already deposited with the tender shall be adjusted while depositing security deposit. Security deposit shall be released within 30 days of successful completion of guarantee period.
- 7. Earnest Money @ 2% of tendered value is to be deposited along with the Techno commercial bid in the form of DD favouring Bharat Coking Coal Limited payable at Dhanbad. The same shall be refundable after the finalization of the tender for the unsuccessful bidders & for the successful bidder the same shall be adjusted towards the security deposit.
- 8. Safety precaution should be taken by the tenderer in case of jobs to be done at our site. Safety aspects will be sole responsibility of the tenderer. The persons deployed by the tenderer for the work at our site must be VTC trained and their names/attendance will be required to be marked in form B/D/E before engaging them at our site.
- 9. LD Clause: Liquidity damages will be charged @ ½ % per week or part there-of subject to maximum of 10 % of the total awarded value for delay in completion of work. The same LD clause will apply to the delay in repair/replacement incase of failure under warranty/guarantee.
- **10. Validity of the offer:** 90 days from the opening of the Tender.
- 11. Rates must be written in figures & words. If there is a variation, the rates written in words shall be considered only. Government taxes may be deducted at source as per rule/guideline.

- 12. All materials, equipment, tools & tackles along with the manpower required for the work will be required to be arranged by the tenderer at his own cost. Only Crane & electricity will be provided whenever needed for work at site, free of cost. The requirement must be for a specific period & in advance by one day in case of crane.
- **13.** All the required documents are to be submitted along with techno commercial bid. The price bid should contain the price only along with the price breakup.
- 14. The tenderer must clearly indicate the nature & details of work in the tender submitted by them. All submitted documents must be signed by the tenderer. The tenderers are advised to do their own page numbering & also enclose a list of enclosures. All envelops must be super scribed with the tender notice no., name of work & type of bid & the bids should be sealed. The tenderer or their authorized representative may be present at the scheduled time of opening of tenders & their presence shall be noted.
- **15.** Tenders may be rejected if the required documents are not enclosed. Right to accept or reject any or all the tenders is reserved without assigning any reason thereof.
- **16.** The firms will be required to mention the name of their authorized person with the contact number to whom the contact can be made in case failure under warranty. The information thus given shall be followed by information in writing. However, the time of failure shall start from the time the information is given over telephone.

Area Manager Excvn) Block-II Area, BCCL