



**Bharat Coking Coal Limited**  
(A Subsidiary of Coal India Limited)  
**Office of the General Manager, Block-II Area**  
**Block-II Area, P.O: Nudkhurkee, Dhanbad**

**Ref No: GM/B-II/Pur/10-11/308**

**Date: 14.10.10**

To,  
The Manager (System),  
EDP Deptt.,  
Koyla Bhawan

Sub: Corrigendum

Ref: GM/BII/Pur/10-11/Website/56, Dated: 28.09.10

Dear Sir,

With Reference to the above NIT no. amendment is being issued for rectification of item details given earlier by our forwarding letter no: GM/B-II/Pur/10-11/Website/280, Dated: 30.09.10. Details of item will be as noted below:

In place of existing entries	Read as
Chain link Assembly for middling elevator 1250 mm without bucket. Each set consisting of: a) Link (Inner) 02 Nos. } EN-19 b) Link (Outer) 01 Nos. } c) Pin 02 Nos. } EN-8 d) Bush with split pin 04 Nos. }	Chain link Assembly for middling elevator 1250 mm without bucket. Each set consisting of: e) Link (Inner) 02 Nos. } EN-19 f) Link (Outer) 14 Nos. } g) Pin 02 Nos. } EN-8 h) Bush with split pin 04 Nos. }

**Note:**

1. All other terms & conditions in above mentioned NIT will remain unchanged
2. Please confirm regarding rectification of item details after uploading in BCCL website

**Encl:**

1. Xerox copy of forwarding letter
2. Xerox copy of above NIT

**Material Manager(Pur)**  
**Block-II Area**