

BHARAT COKING COAL LIMITED
(A Subsidiary of Coal India Limited)
Office of the General Manager:Barora Area
Excavation Department
P.O. Nawagarh,Dist.DHANBAD-828306

Ref no: GM/BA/AM(Excvn)/NIT/11-12/ **531**

Dated: 10/11-05-2011

NOTICE INVITING TENDER

Sealed tenders are invited from reputed electrode manufacturers/reclaimers in 2 bid system (Techno-commercial & price bid) from experienced contractors/repairers for undertaking the following repair job of Barora Area, BCCL

| Sl no | Description of job | Estimated value of tender (Rs.) | Earnest money (1% of estimated value) (Rs.) | Last date & time for submission of tender | Date & time of opening of tender | Work completion period | Minimum Warranty/ Guarantee |
|-------|--|---------------------------------|---|---|----------------------------------|---|--|
| 1. | Repairing / Strengthening of Dipper Body Assly. of 182M Marion (10 M ³) Shovel, Sl.No.221 , BCCL No.S-308 of Muraidih OCP. | 2,29,163=00 | 2292=00 | 08.06.11 up to 3.00 p.m. | 08.06.11 at 4.30 p.m. | 15 days from issue of work order or handing over of job for repair whichever is later | 1000 hrs or 06 months from the date of completion & handing over of the work whichever is later. |

Tender paper & Tender document will be issued from **01.06.11 to 07.06.11** during office hours from the Office of the Area Manager (Excvn), Barora Area, BCCL upon submission of DD for Rs.250.00(Rs Two hundred fifty only) payable to Bharat Coking Coal Limited payable at Dhanbad or by deposition of cash at Cash Section of Barora Area. The rest of the details like terms & conditions are in the Tender Document. The tender documents are to be submitted in the tender box placed in the Office of the Area Manager (Excvn)), Barora Area. **Tenderers must submit their Bank A/c. details in prescribed format which will be issued alongwith tender document. Failure to submit the same by the bidder, his offer may be liable to be rejected** The sale of tenders shall be stopped one day prior to the last day of submission of tender. The tenderers may inspect the item for repair at **Muraidih OCP** on any working day during working hours prior to submission of tenders.

SCOPE OF WORK:

A. Repairing of Dipper Body:

(1) Repairing of LH Dipper corner by cutting/ gauging & welding with suitable electrode. (2) Repairing of Dipper front hinges (for 'C' frame) by cutting/ gauging & welding with suitable electrode. (3) Repairing of Dipper rear hinges (for Door) by cutting/ gauging & welding with suitable electrode. (4) Strengthening of front & rear hinges by welding with extra plate . (5) Repairing of Dipper lip. (6) Repairing of Dipper body front top portion. (7) Strengthening of both sides Dipper heel band inside & outside. (8) Strengthening of front top by welding with extra 16 mm plate. (9) Strengthening of Dipper front wall (inside & outside).

B. Repairing of Door Assy:

(1) Repairing of Door lower portion plate. (2) Repairing of Door lower portion rear box. (3) Repairing of Latch foundation & fulcrum. (4) Strengthening of Door front & rear by welding with extra 12 mm plate.

C. Repairing of Bore & Fitting of Bushing: Repairing of 20 Nos bore & bush fitting.

D. Others: Others job related to above as required.

Note: Job has to be done at site (Muraidih OCP) and only electric supply will be provided by BCCL.

Area Manager (Excvn)
Barora Area, BCCL

Copy to:

(1) GM / AGM / AFM, Barora Area. (2) G.M.(Excvn), Koyla Bhawan.
(3) Sr. Manager (System), Regional Stores, Barora Area—For publication of tender on web site as per laid down procedure. (4) Notice Board-Barora Area. (5) Notice Board, All Areas of BCCL.