

BHARAT COLING COLA LIMITED
(A SUBSIDIARY OF COAL INDIA LIMITED)
OFFICE OF THE GENERAL MANGER, BLOCK II AREA
P.O. NAWAGARH DIST; DHANBAD

GM:BII:EXCV:NIT::09: 90/2800

Date: 15.10.09

NOTICE INVITING TENDER

16

Sealed tenders are invited from reputed/electrod manufacturers/reclaimers in two bid system (Technical bid & price bid) for undertaking the following repair job of block II area of BCCL.

N.	Description of job	Estimated value(Rs)	Earnest money 1% of the est. value	Date if receipt	Date of opening	Completion period	Warranty
	Rep/rebuilding the V groove of Deflection pulley(2 nos) and A frame pulley(2 nos) of 24/96 dragline. of BOCP.	211650/-	1%	6.11.09	6.11.09	20 days	2500 w/hours or 12 months from the date of commissioning whichever is earlier

Issue of tender documents--26.10.09-30.10.09- Tender cost : Rs 100/-:

1. Eligibility: The tender must have experienced of similar work during last seven years ending last day of the previous to the one in which tenders are invited should be any one of the following:

- i) Three similar completed works each costing not less than the amount equal to estimated cost.
- ii) Two similar completed work not less than the amount equal to 50% of the estimated value.
- iii) One similar completed work each costing not less than the amount equal to 80% of the estimated cost.

2. Average annual financial turnover during the last financial year ending 31st March of the previous financial year should be atleast 30% of the estimated cost.

3. Security deposit and performance guarantee 10% (including earnest money of work order amount to be deposited within 10 days of issue of work order by the qualified tenders. The earnest money will be retained as performance guarantee which will be released after satisfactory completion of warranty period.

4. The tenders must have valid sale tax registration/VAT/TIN/Service Tax registration and latest copy of Income tax return filed along with PAN.

5. Payment : 100% will be made after satisfactory completion work on submission of bill.

6. Safety precaution should be taken by the repairer. Safety aspect will be sole responsibility of the repairers. The contractors person must trained t VTC and their knames/ttendance must be mrlked in form B/D/E before engaig them in mines

7. The earnest money can be deposited in form of cash to area Finance Manager, Block II Area or in the shape of DD/Bankers cheque in favour of Bhart Coking Coal Limited payable at Dhanbad issued k from any nationalized bank will also be accepted.

8. The enders will be received up to 1.00 P.M. on the scheduled date and will be opened at 3.00 P.M. on the same date

9. The terms similar work stand for HEMM repairing involving repairing etc.

Area Manager(Excv)
Block II Area

CC: GM/AGM/AFM, BII Area

CC: Noticer board All Area

CC: Notice Board Block II Area

CC: PR, Koyla Bhawan- alongwith 5 copies of NIT & 2 copies of Tender documents for wide publication on web site and leading news papers.