

**BHARAT COKING COAL LIMITED**  
(A SUBSIDIARY OF COAL INDIA LIMITED)  
OFFICE OF THE CHIEF GENERAL MANAGER  
BLOCK-II AREA, PO- NAWAGARH, DIST- DHANBAD

No-CGM/B-II/EXCVN/NTT/08/ 167/6465

Dt- 28/1/2009

Sealed tenders are invited from reputed electrode manufacturer/reclaimers in two ~~bid~~ system (TC bid and Price bid) for undertaking the following repair job of Block-II Area of BCCL-

Sl no	Description of job	Estimated value (Rs)	Earnest money (Rs)	Last date of receipt of tender	Date of opening of tender	Cost of tender document	Job Completion period	Warranty
1	Repairing of bucket assy of P&H shovel of BOCP.	Rs 192000/-	1% of estimate	25.2.09 by 1 P.M.	25.2.09 at 3.00 P.M.	100=00	20 days	1500 w/hr or, 12 months from the date of commissioning which-ever comes earlier.

Issue of tender document- up to 16.2.09 to 21.2.09

(On all working days during working period except on Sunday/Holiday)

1) Eligibility -The tenderer must have experience of successfully completed similar work during last seven years ending last day of the month previous to the one in which tenders are invited should be any one of the following-

i) Three similar completed works each costing not less than the amount equal to 40% of the estimated cost.

ii) Two similar completed works each costing not less than the amount equal to 50% of estimated cost.

iii) One similar completed work costing not less than the amount equal to 80% of the estimated cost.

2) Average annual financial turn over during last three years ending 31<sup>st</sup> March of the previous financial year should be at least 30% of the estimated cost.

3) Security deposit and performance guarantee- 10% (including earnest money) of work order amount to be deposited within 10 days of issue of work order by qualified tenderer. The earnest money will be retained as security money, the qualified tenderer will have to deposit additional amount. After completion of work, this amount will be retained as performance guarantee which will be released after satisfactory completion of guarantee period.

4) The tenderer must have valid sale tax registration/VAT/TIN, service tax registration and latest copy of income tax return filed along with PAN.

5) Payment - 100% payment will be made after satisfactory completion of work on submission of bill.

6) Safety precaution should be taken by the repairer. Safety aspect will be the sole responsibility of the repairer. The contractor persons must be trained at VTC and their names/attendances must be marked in form 'B/D/B' before engaging them in mines.

7) The details of job, terms and conditions will be available in tender documents.

8) The tender documents can be had from the office of Area Manager (Excv), Block-II Area on submission of cash of requisite amount to Area Finance Manager, Block-II Area or demand draft /banker's cheque of requisite amount in favour of 'Bharat Coking Coal Limited' payable at Dhanbad issued from any nationalized bank. It can be downloaded from website of BCCL.

9) The tenders will be received up to 1.00 P.M. on the scheduled date and will be opened at 3.00 P.M. on the same date.

10) Tenderers may submit their offer for one or more job but they are required to submit separate set of offer for each job.

11) The term similar work stands for HEMM repairing involving repair/ welding etc.

  
Area Manager (Excv),  
Block-II Area, BCCL

CC-1)GM/AGM/AFM Block-II Area

1) Notice Board-All Areas

3) Notice Board-Block-II Area

4) CGM(Excv)/Koyla Bhavan

5) PRO/Koyla Bhavan—along with i) 5 copies of tender notice for wide publication on website and news paper ii) 2 copies of tender document for placing on web site.

