



BHARAT COKING COAL LIMITED
(A Subsidiary of Coal India Limited)
Office of the General Manager
Block-II Area: P.O. Nawagarh DHANBAD

Ref no: GM/BII/Excvn/NIT/10/138/3670

Dated: 20/01/11

NOTICE INVITING TENDER

Sealed tenders in two-bid system (Techno-commercial & price bid) are invited from experienced contractors/repairers for undertaking the following repair job of Block-II Area, BCCL

Sl n o	Description of job	Estimated value of tender	Earnest money (2% of estimated value)	Last date & time for submission of tender	Date & time of opening of tender	Work completion period/contract period	Min. Warranty/Guarant ee
1	Repair of failed saddle block assembly(1 no LHS & 1 no RHS) of P&H 1900AL Shovel	253040.00	5061.00	16/02/11 up to 1.00 p.m	16/02/11 .at 3.30 p.m.	20 days from the date of issue of work order/handing over of item for repair whichever is later	1000 hrs or 06 months from the date of completion & handing over of the work which ever earlier

Tender paper & Tender document will be issued from **01/02/11 to 15/02/11** during office hours from the Office of the Area Manager (Excvn), Block-II Area, BCCL upon submission of DD for Rs.250.00 (Rs two hundred & fifty only) payable to Bharat Coking Coal Limited payable at Dhanbad. The rest of the details like terms & conditions are in the Tender Document. The tender documents to be submitted in the tender box placed in the Office of the Area Manager (Excvn), Block-II Area. The sale of tenders shall be stopped one day prior to the last day of submission of tender. **The tenderers may inspect the item for repair at RRWS on any working day during working hours prior to submission of tenders**

SCOPE OF WORK:

1. Cleaning of complete assembly & removal of the worn out bushes from the saddle block.
2. Repairing of the oval bushing housing by undercutting of bore by horizontal boring process, metal deposition on the under cut bore with suitable electrodes & reboring to correct bushing size. Bushing collar seat of saddle block to be rebuilt & machined to standard desired size. Repairing of cracks in the bore as well as the base plate.
3. Dowel hole reconditioning & providing Dowel pins
4. Repairing of ovality of slide plate fixing bolt holes & providing the required bolts.
5. Cleaning of all lubrication line holes & fitment of all related lubricating tubes, elbows, etc
6. Providing & fitment of 4 nos bushing(Part no 5T2787)
7. Pulley bracket with pulley to be provided & fitted in one saddle block

General Manager (Excvn)
Block-II Area, BCCL

CC:

1. General Manager, Block-II Area
2. Chairman(TC)/A.M(Plg.), Block-II Area/Area Manager(Excvn) of all Areas of BCC
3. Notice Boards of Area Office: Barora, Block-II, Govindpur, Katras, Sijua, Kusunda, Putki-Balihari, Kustore, Bastacola, Lodna, Eastern Jharia, Chanch Victoria, Western Jharia, & other Areas of BCCL
4. Notice Board: Block-II OCP, Jamunia OCP, RRWS
5. Sr.Systems Officer, Koyla Bhavan BCCL to upload the tender in Website & publish in



BHARAT COKING COAL LIMITED
(A Subsidiary of Coal India Limited)
Office of the Chief General Manager
Block-II Area: P.O. Nawagarh DHANBAD

Ref no: GM/BII/Excvn/NIT/10/138/3670

Dated: 20/01/10

TENDER DOCUMENT

1. **ELIGIBILITY:** The tenderer must have experience of **SIMILAR** work during last seven years ending last day of previous year to the one in which tenders are invited as any one of the following
 - a. Three similar completed works each not less than 40% of the estimated value of the tender.
 - b. Two similar completed work each not less than 50% of estimated value of the tender.
 - c. One similar completed work not less than the amount equal to 80% of the estimated value of the tender.

SIMILAR works means re-building, grinding, machining, hardening, press fitting, etc. of the parts of the HEMM whichever is applicable.

2. The average annual financial turn over during the last 3 financial years ending 31st March should be at least 30% of the estimated value.
3. The tenderers must submit copy of valid Sales Tax registration, VAT/CST registration, TIN registration, Service Tax registration along with copy of PAN of the firm/proprietor. The submitted documents should be attested by a NOTARY.
The tenderer shall be barred from taking part in the future tender, if any documents/information submitted by the tenderer is found to be incorrect/false.
4. **WARRANTY:** If any item repaired against the work order fails because of poor workmanship or quality, the same shall be replaced/repared free of cost within 15 days failing which the LD clause as in sl no 9 will be applicable & the company shall have the power to recover the total repairing cost of the failed items from any of the pending bills of the repairer.
5. **PAYMENT:** 100% payment will be made within 30 days of submission of bill after completion & acceptance of job. The firms will be required to submit along with the TC bid the bank details in the prescribed format in triplicate which will be provided along with the tender documents. The details may be provided in the original copy or through photo copies (at least one should be attested by a Notary).

SECURITY DEPOSIT: 10% of the total value of the work order shall be deposited by the repairer in the form of Bank Draft before starting the job. Earnest money already deposited with the tender shall be adjusted while depositing security deposit. Security deposit shall be released within 30 days of successful completion of guarantee

7. Earnest Money @ 2% of tendered value is to be along with the Techno commercial bid in the form of DD favoring Bharat Coking Coal Limited payable at Dhanbad. The same shall be refundable after the finalization of the tender for the unsuccessful bidders & for the successful bidder the same shall be adjusted towards the security deposit.
8. Safety precaution should be taken by the tenderer in case of jobs to be done at our site. Safety aspects will be sole responsibility of the tenderer. The persons deployed by the tenderer for the work at our site must be VTC trained and their names/attendance will be required to be marked in form B/D/E before engaging them at our site.
9. **LD Clause:** Liquidity damages will be charged @ ½ % per week or part there-of subject to maximum of 10 % of the total awarded value for delay in completion of work. The same LD clause will apply to the delay in repair/replacement incase of failure under warranty/guarantee.

10. Validity of the offer: 90 days from the opening of the Tender.
11. Rates must be written in figures & words. If there is a variation, the rates written in words shall be considered only. Government taxes may be deducted at source as per rule/guideline.
12. All materials, equipment, tools & tackles along with the manpower required for the work will be required to be arranged by the tenderer at his own cost. The brand & make of the electrodes used if any will have to be mentioned in the bids. Only Crane & electricity will be provided whenever needed for work at site, free of cost. The requirement must be for a specific period & in advance by one day in case of crane.
13. All the required documents are to be submitted along with techno commercial bid. The price bid should contain the price only along with the price breakup.
14. The tenderer must clearly indicate the nature & details of work in the tender submitted by them. All submitted documents must be signed by the tenderer. The tenderers are advised to do their own page numbering & also enclose a list of enclosures. All envelopes must be super scribed with the tender notice no., name of work & type of bid & the bids should be sealed. The tenderer or their authorized representative may be present at the scheduled time of opening of tenders & their presence shall be noted.
15. Tenders may be rejected if the required documents are not enclosed. Right to accept or reject any or all the tenders is reserved without assigning any reason thereof.
16. The firms will be required to mention the name of their authorized person with the contact number to whom the contact can be made in case failure under warranty. The information thus given shall be followed by information in writing. However, the time of failure shall start from the time the information is given over telephone.

General Manager (Excvn)
Block-II Area, BCCL