

Ref. No. BCCL/BA-IX/E&M/TE/F-37/Sep/17-18/151

Dated: 08-09-2017

**TENDER NOTICE**

Sealed tenders are hereby invited from the experience , reliable and financially sound Repairer/Contractor for the following works , details given below.

Description of work	Location	Estimated Contract Value ( ₹ )	Earnest Money of total amount ( ₹ )	Cost of T/Paper ( ₹ )	Period
Repairing of (Hywa) No.JH10AF-3537	Bera Colliery	48,780/=	1.25% of the Estimated Cost	50/=	25 Days

**Details of GST Registration of BCCL :**

GSTIN of BCCL	West Bengal (WB)	Jharkhand (JH)
	19AAACB7934M2Z7	20AAACB7934MFZB
PAN	AAACB7934M	
Address of Principal Place of Business	Bharat Coking Coal Ltd. 6, Lyons Range, Kolkata, West Bengal-700001	Bharat Coking Coal Ltd., Koyla Bhawan, Koyla Nagar,Dhanbad, Jharkhand-826005

**Terms and Conditions :-**

- The Tender paper/BOQ can be had from the office of the undersigned on any working day on production of money receipt for the cost of tender paper (Non-refundable). For downloaded tender documents requisite money receipt of tender paper cost may please be submitted along with the tender documents. The date of issue of tender paper from 23-09-2017 to 26-09-2017 up to 1.00 P.M.
- The sealed Tender / Offer in a single envelope containing in three parts i.e. Part-I (Earnest Money) , Part-II (Technical Bid) & Part-III (Price Bid). Envelops of Part-I, Part-II & Part-III should be superscribed with due date, Tender Notice No. etc. .Tender will be received in the Tender Box kept in the office of Area Manager (E&M), Bastacolla Area positively upto 1.00 PM on 28-09-2017. The technical Bid i.e Part-II will be opened only after opening of Part-I (Earnest Money) if found as per NIT at 3.00 PM on the same date. Price will be opened only after acceptance of the technical Bids. The Bidders have to submit the affidavit only on Non-judicial Stamp paper or Non-Judicial Adhesive Stamp as per Performa given in Annexure-I.
- Earnest money @1.25% of the estimated cost value should be deposited in Finance Deptt. in cash/bank draft drawn in favour of "BHARAT COKING COAL LTD., payable at Dhanbad and a photo copy (Self attested) money receipt is to be enclosed with the tender. Tenderer will be liable for rejection without earnest money. **In case where EMD is not submitted by the bidder along with their bids, the bidder will be debarred from participating in future tenders for 6(Six) months.** NSIC holding firms and Ancillary Unit of BCCL will be exempted from Cost of tender paper, Earnest Money etc. as per norms of the Company. The Bids sent by post will not be accepted.

**Contd.....2.....**

4. Earnest money deposited by the contractor will not carry any interest and will be refunded to the unsuccessful tenderer and for successful tenderer it will be converted to security deposit and will be refunded without any interest after successful completion of guarantee period.
5. Experience of having successfully completed similar nature of works during last 7 (Seven) years ending last of the month previous to the one in which Bids are invited should be either of the following:
  - a. Three similar completed works each costing not less than the amount equal to 40% of the estimated cost,

OR,

  - b. Two similar completed works each costing not less than the amount equal to 50% of the estimated cost,

OR,,

  - c. One similar completed work each costing not less than the amount equal to 80% of the the estimated cost
6. Average annual financial turnover during the last three years, ending, 31<sup>st</sup> March of the previous financial year should be at least 30% of the estimated cost.
7. Similar job means: Vehicle Repair work
8. Guarantee period will be normally SIX MONTHS , however may vary depending upon the job.
9. Tenderer should enclosed GSTin ,PAN No & SSI Registration/ DGMS/Valid Electrical Licence approval in their offer, if applicable
10. Validity of NIT : 120 Days
11. Bank Account Details .
12. GST – As applicable
13. Tenderers may contact the undersigned during office hours if required for any further clarification before submission of their offer/tender.
14. The tender documents can be downloaded from our website [www.bcclweb.in](http://www.bcclweb.in)
15. The Management is not under any obligation to accept the lower tender(s) and reserve the right to accept or reject any or all the tender(s) without assigning any reason whatsoever , at its  
sold discretion.
16. Matters relating to any dispute or difference(s) arising out of this tender and subsequent contract awarded based on the tender shall be subject the jurisdiction of District Court, Dhanbad , Jharkhand.

Nodal Officer  
Bastacolla Area-IX

**C.c.to:**

1. Manager (System),Bastacolla- For uploaded in Website before 23-09-2017.
2. Area Manager (E&M), Barora/Govindpur /Block-II/Katras/Sijua/Kusunda/ PB/Lodna/WJ(Moonidih)/EJ/CV Area.- with a request to download this NIT and display in their respective notice board .
3. Notice Board, Bastacolla Area-IX
4. Office copy

**Bharat Coking Coal Limited**  
(A subsidiary of Coal India Ltd)

**Bastacolla Area No. –IX**

BCCL/BA-IX/E&M/TE/F-37/Sep/17-18/151

Dated : 08-09-2017

Repairing of (Hywa) No. JH10AF-3537 of Bera Colliery.

Nodal Officer,  
Bastacolla Area

Sl. No.	Description	Qty	Rate Rs.	Amount Rs.
---------	-------------	-----	----------	------------

**Labour and Making Cost**

1	Complete clutch system overhauling, removing & Fitting.	1 Set.		
2	Clutch & Brake Paddle complete dismantling, removing & Fitting, setting.	1 Set.		
3	Acceletter Paddle complete dismantling, removing, fitting & setting.	1 No.		
4	Steering system complete dismantling, removing & fitting.	1 Set.		
5	Steering chassis Box complete welding & Repairing.	1 No.		
6	Steering chassis Box complete straightaning proper Aligning	1 No.		
7	Rear & Front Engine mounting, removing Bolt changing, fitting.	2 Nos.		
8	Front both side wheel Mudguard cutting, denting, welding, repairing, removing & Fitting.	2 Nos.		
9	Cabin Floor cutting, welding, straightaining & repairing.	1 No.		
10	Rear Both side wheel Mudguard cutting, welding, repairing, straightaining, removing & fitting.	2 Nos.		
11	Driver, Co-driver Seat new making, Rexine cover with Foam replacement, Fitting best quality.	4 Nos.		
12	Complete vehicle Nipple greasing.	1 No.		
			<b>Total</b>	

**Spares/Material Cost**

1	Clutch Plate	1 No.		
2	Clutch Pressure Plate repairing kit	1 Set.		
3	Clutch housing Bolt	4 Nos.		
4	Clutch Bearing with hub	1 Set.		
5	Clutch Cylinder repairing kit	1 Set.		
6	Clutch release yoke	1 No.		
7	U.J. Cross Holder	1 No.		
			<b>Total</b>	
	Labour & Making Cost			
			<b>G.Total</b>	

**Signature of Contractor with seal and Address.**