

Ref. No. BCCL/BA-IX/E&M/TE/F-37/Sep/17-18/154

Dated: 08-09-2017

TENDER NOTICE

Sealed tenders are hereby invited from the experience , reliable and financially sound Repairer/Contractor for the following works , details given below.

Description of work	Location	Estimated Contract Value (₹)	Earnest Money of total amount (₹)	Cost of T/Paper (₹)	Period
Repairing of (Tata) make Water Tanker No.BHW-1931.	ROCP/SJ	46,828/=	1.25% of the Estimated Cost	50/=	20 Days

Details of GST Registration of BCCL :

GSTIN of BCCL	West Bengal (WB)	Jharkhand (JH)
	19AAACB7934M2Z7	20AAACB7934MFZB
PAN	AAACB7934M	
Address of Principal Place of Business	Bharat Coking Coal Ltd. 6, Lyons Range, Kolkata, West Bengal-700001	Bharat Coking Coal Ltd., Koyla Bhawan, Koyla Nagar,Dhanbad, Jharkhand-826005

Terms and Conditions :-

- The Tender paper/BOQ can be had from the office of the undersigned on any working day on production of money receipt for the cost of tender paper (Non-refundable). For downloaded tender documents requisite money receipt of tender paper cost may please be submitted along with the tender documents.The date of issue of tender paper from 23-09-2017 to 26-09-2017 up to 1.00 P.M.
- The sealed Tender / Offer in a single envelope containing in three parts i.e. Part-I (Earnest Money) , Part-II (Technical Bid) & Part-III (Price Bid). Envelops of Part-I, Part-II & Part-III should be superscribed with due date, Tender Notice No. etc. .Tender will be received in the Tender Box kept in the office of Area Manager (E&M), Bastacolla Area positively upto 1.00 PM on 28-09-2017.The technical Bid i.e Part-II will be opened only after opening of Part-I (Earnest Money) if found as per NIT at 3.00 PM on the same date. Price will be opened only after acceptance of the technical Bids. The Bidders have to submit the affidavit only on Non-judicial Stamp paper or Non-Judicial Adhesive Stamp as per Performa given in Annexure-I.
- Earnest money @1.25% of the estimated cost value should be deposited in Finance Deptt. in cash/bank draft drawn in favour of "BHARAT COKING COAL LTD., payable at Dhanbad and a photo copy (Self attested) money receipt is to be enclosed with the tender. Tenderer will be liable for rejection without earnest money. **In case where EMD is not submitted by the bidder along with their bids, the bidder will be debarred from participating in future tenders for 6(Six) months.**NSIC holding firms and Ancillary Unit of BCCL will be exempted from Cost of tender paper, Earnest Money etc. as per norms of the Company. The Bids sent by post will not be accepted.

Contd.....2.....

4. Earnest money deposited by the contractor will not carry any interest and will be refunded to the unsuccessful tenderer and for successful tenderer it will be converted to security deposit and will be refunded without any interest after successful completion of guarantee period.
5. Experience of having successfully completed similar nature of works during last 7 (Seven) years ending last of the month previous to the one in which Bids are invited should be either of the following:
 - a. Three similar completed works each costing not less than the amount equal to 40% of the estimated cost,

OR,

 - b. Two similar completed works each costing not less than the amount equal to 50% of the estimated cost,

OR,,

 - c. One similar completed work each costing not less than the amount equal to 80% of the the estimated cost
6. Average annual financial turnover during the last three years, ending, 31st March of the previous financial year should be at least 30% of the estimated cost.
7. Similar job means: Vehicle Repair work
8. Guarantee period will be normally SIX MONTHS , however may vary depending upon the job.
9. Tenderer should enclosed GSTin ,PAN No & SSI Registration/ DGMS/Valid Electrical Licence approval in their offer, if applicable
10. Validity of NIT : 120 Days
11. Bank Account Details .
12. GST – As applicable
13. Tenderers may contact the undersigned during office hours if required for any further clarification before submission of their offer/tender.
14. The tender documents can be downloaded from our website www.bcclweb.in
15. The Management is not under any obligation to accept the lower tender(s) and reserve the right to accept or reject any or all the tender(s) without assigning any reason whatsoever , at its
sold discretion.
16. Matters relating to any dispute or difference(s) arising out of this tender and subsequent contract awarded based on the tender shall be subject the jurisdiction of District Court, Dhanbad , Jharkhand.

Nodal Officer
Bastacolla Area-IX

C.c.to:

1. Manager (System), Bastacolla- For uploaded in Website before 23-09-2017.
2. Area Manager (E&M), Barora/Govindpur /Block-II/Katras/Sijua/Kusunda/ PB/Lodna/WJ(Moonidih)/EJ/CV Area.- with a request to download this NIT and display in their respective notice board .
3. Notice Board, Bastacolla Area-IX
4. Office copy

Bharat Coking Coal Limited
(A subsidiary of Coal India Ltd)

Bastacolla Area No. –IX

BCCL/BA-IX/E&M/TE/F-37/Sep/17-18/154

Dated : 08-09-2017

Repairing of (Tata) make Water Tanker No. BNW-1931 of ROCP/SJ

Nodal Officer,
Bastacolla Area

Sl. No.	Description	Qty	Rate Rs.	Amount Rs.
---------	-------------	-----	----------	------------

Labour and Repairing Cost

1	Both side Mudguard Flaf new making, Fitting.	2 Nos.		
2	Both side head Light show mudguard complete Denting, Welding & sheet changing.	16 Sq.ft.		
3	Both side complete Footrest with Marshal Sheet replaceing, Cuting, welding & denting.	12 Sq.ft.		
4	Battery Box denting, welding & Sheet changing.	8 Sq.ft.		
5	Complete Engine bonnat denting, welding and reshaping, repairing.	16 Sq.ft.		
6	Both side Door Pillar denting, welding & sheet changing (outer Inner side)	20 Sq.ft.		
7	Both side (outer inner) Door denting, welding & sheet changing.	15 Sq.ft.		
8	Door Kabja bracket cutting, welding, fitting & repairing.	4 Nos.		
9	Both side Door with Piller (Inner Side) channel cutting, welding and new channel making, fitting, welding including all materials.	2 Sets		
10	Complete cabin Dashboard (Outer Inner) side Painting selected colour Best Quality (03) three Coats with Letter writing including all materials with Labour cost.	1 No.		
11	linner side) cabin back channel rushted cutting, welding and new channel making, fitting, welding including all materials with labour cost.	1 No.		
12	Front Bumper complete denting, welding & repairing, removing and fitting.	1 No.		
13	Front Bumper bracket cutting, welding, repairing, removing & fitting.	2 Nos.		
14	Complete vehicle Servicing & Greasing.	1 No.		
15	Complete cabin ceiling new making including all materials with labour cost.	1 No.		

Sl. No.	Description	Qty	Rate Rs.	Amount Rs.
---------	-------------	-----	----------	------------

Labour and Repairing Cost

16	Driver Seat new making rexine cover with foam replacing including all materials.	2 Nos.		
17	Co-Driver Seat new making rexine cover with foam replacing including all materials.	2 Nos.		
18	Co-Driver Seat new wooden Plank new making, fitting including all materials.	2 Nos.		
19	Both side Piller Konia new making, cutting, welding, fitting.	2 Nos.		
20	Complete Cabin Dashboard under body channel replacing, cutting, welding, fitting, making including all materials.	1 No.		
21	Complete cabin Dashboard removing and fitting from on chassis also all accessories removing and fitting.	1 No.		
22	Cabin Top side Denting, welding & Sheet changing.	15 Sq.ft.		
23	Cabin back side (outer inner) denting, welding & sheet changing.	20 Sq.ft.		
24	Cabin Floor denting, welding & Sheet changing.	12 Sq.ft.		
25	Front both side wheel Mudguard cutting, denting & sheet changing.	16 Sq.ft.		
			Total	

Signature of Contractor with seal and Address.