

**BHARAT COKING COAL LIMITED**  
(A Subsidiary of Coal India Limited)  
Office of the General Manager:Barora Area  
Excavation Department  
P.O. Nawagarh,Dist.DHANBAD-828306

Ref no: GM/BA/AM(Excvn)/NIT/11-12/ **2788** / Dated: 10/12.08.2011

**NOTICE INVITING TENDER**

**Sealed tenders in 2 bid system (Techno-commercial & price bid) are invited from experienced contractors/repairers for undertaking the following repair job of Barora Area, BCCL.**

Sl no	Description of job	Estimated value of tender (Rs.)	Earnest money (1 % of estimated value) (Rs.)	Last date & time for submission of tender	Date & time of opening of tender	Work completion period	Minimum Warranty/ Guarantee
1.	Repairing of Under Carriage, Crowd Machinery & Machine Housing of EKG shovel Sl.No.HMB-391, BCCL No.S-265 of Muraidih OCP	2,07,500=00	2075=00	09.09.11 up to 3.00 p.m.	09.09.11 at 4.30 p.m.	15 days from issue of work order or handing over of job for repair whichever is later	1000 hrs or 06 months from the date of completion & handing over of the work whichever is later.

Tender paper & Tender document will be issued from **02.09.11 to 08.09.11** during office hours from the Office of the Area Manager (Excvn), Barora Area, BCCL upon submission of DD for Rs.250.00(Rs Two hundred Fifty) payable to Bharat Coking Coal Limited payable at Dhanbad or by deposition of cash at Cash Section of Barora Area. The rest of the details like terms & conditions are in the Tender Document. Sealed tenders are to be submitted in the tender box placed in the Office of the Area Manager (Excvn), Barora Area. **Tenderers must submit their Bank A/c. details in prescribed format which will be issued alongwith tender document. Failure to submit the same by the bidder, his offer may be liable to be rejected.** The sale of tenders shall be stopped one day prior to the last day of submission of tender. The tenderers may inspect the item for repair at **Muraidih OCP** on any working day during working hours prior to submission of tenders.

**SCOPE OF WORK:-**

- (1). Dismantling & fitting of LHS driving shaft bushing with bore. (2) Dismantling & fitting of RHS driving shaft bushing with bore. (3) Repairing of LHS intermediate shaft with lock. (4) Repairing of LHS & RHS driving shaft. (5) Repairing of both sides propel driving gear. (6) Repairing of both sides driving pinion. (7) Repairing of propel rollers with bore and side—6 Nos. (8) Repairing of propel roller bearing axle with lock by welding & grinding—6 Nos. (9) Repairing of crowd machinery with replacement of motor pinion and repairing of foundation by welding, grinding and setting. (10) Fabrication of steel washer and retainer for under carriage—30 Nos. (11) Repairing of machine housing, counter weight and hand rails (total:130 Sq.ft.).

G.M.(Excvn) / Area Manager (Excvn)  
Barora Area, BCCL

**Copy to:**

- (1) GM / AGM / AFM, Barora Area. (2) G.M.(Excvn), Koyla Bhawan.  
(3) Sr. Manager (System), Regional Stores, Barora Area—For publication of tender on web site as per laid down procedure. (4) Notice Board-Barora Area. (5) Notice Board, All Areas of BCCL.