

(A Subsidiary of Coal India Limited)

Bhuli Town Administration

Bhuli : Dhanbad- 828104 PHONE NO. 0326-2340420, 2340341

Ref.No.BCCL/BTA/Bhuli/2011/61

Date-10/06/2011.

QUOTATION NOTICE.

Sealed Quotation on Percentage Rate Above or Below basis are invited from the reputed contractors for the following works and the same will be received from 11.00 A.M. to 3.00 P.M. on 27.6.2011 and opened on 12.00 Noon on 29.6.2011 at the office of the Area Manager ,BTA in the presence of intending tenderers or their authorized representatives. B.O.Q. for the job can be obtained from the office of the Area Manager ,BTA during working hours from 24.6.11 to 25.6.2011 . The Quotation is also available on Website http://bccl.cmpdi.co.in and can be downloaded. The other documents such as General terms & conditions and responsibility of the contractors, additional safety measures etc. also can be seen at the office of A.M.(BTA),Bhuli Town Admn.,Bhuli on Any working day which will be applicable to the contract . The details of works are given below:-

Sl.No	Name of work	Est.Cost.Rs.	Earnest	Time of
			Money Rs.	completion
1.	Repair & Maint. Of Qtr.No.B/50, B/53 & B/54 at Bhuli.	45493.55	455/-	01 Month
2.	For Burial pit in R.H. Bhuli for Bio Medical Waste.	15240.69	153/-	15 days
3.	Rep. & Maint. Of the Qtr.No.C/92 & C/414 at C Block,Bhuli.	27814.63	279/-	15 days
4.	Rep. & Maint. Of B/13 at old B Type Bhuli .	22713.24	228/-	15 days
5.	Rep. & Maint of Qtr. No.C/1 at C Type Qtr.,Bhuli.	9092.83	91/-	15 days
6.	Rep. & Maint. Of Bunglow No.2 near R.H.Bhuli.	22063.03	221/-	15 days

No materials will be issued by the department for this work. The quotation to be submitted in single part. No tender without Earnest Money will be accepted. The Draft of Earnest Money will be after the date of quotation.

The tenderers have to submit Permanent Account Number of Income Tax (PAN NO.) & Tin No.

Dy.CE©BTA

Distribution:-

1)G.M.(Civil)CED,Koyla Nagar. 2.Chief Manager(Civil)CED,Koyla Nagar.3.G.M.(admn.)K.Bhawan.

4. Area Manager, BTA, Bhuli. 5. G.. M. (System) Koyla Bhawan 6. Notice Board, BTA, Bhuli.

7.Concerned File.



(A Subsidiary of Coal India Limited)

Bhuli Town Administration

Bhuli : Dhanbad- 828104

PHONE NO. 0326-2340420, 2340341

BILL OF QUANTITY FOR THE WORK OF R/M OF QTR.NO. B/50, B/53 & B/54 AT BHULI. SL.NO.1

SL.NO	NAME OF ITEM	QTY.	UNIT	RATE RS.	AMOUNT.RS.
1.	12MM th. Cement plaster	113.44 sqm	Sqm.	67.65/sqm	7674.21
	(1:6)dodo.comp. job.				
2.	25MM TH. Cement concrete floor	115.58 sqm	Sqm	86.05/sqm	9945.65
	(1:2:4) do.do.comp.job				
3.	6mm th. Cement plaster (1:3)in.	4.63sqm.	Sqm.	62.15/sqm	287.75
4.	Brick work (1:6) in sup.	2.16 sqm.	Sqm.	2205.05/sqm	4762.90
5.	Half brick work (1:4) in sup.	24.11 sqm.	Sqm.	290.25/sqm.	6997.92
6.	12mm th. Plaster with punning	14.40 sqm.	Sqm.	97.90/sqm.	1409.76
7.	Pre cast RCC slab	0.57 sqm	Sqm.	4882.25/sqm.	2782.88
8.	Reinforcement for RCC work cold	37.00 Kg.	Kg.	42.70/Kg.	1579.90
	twisted bar.				
9.	Brick flat soling on edge floor.	12.00 sqm	Sqm.	196.37/sqm	2356.44
10.	25mm th. Batton door shutter .	1.38 sqm	Sqm.	1320.50/sqm	1822.29
11.	P/F/F Sal wood work in frame.	0.034 cum	Cum	30511.90/cum	1037.40
12.	P/F/F hold fast .	6 Nos.	Each	61.50 each	369.00
13.	White washing two coat on old	471.00 sqm	Sqm.	4.10/sqm.	1931.10
	surface.				
14.	Painting with synthetic enamel	111.00 sqm.	Sqm.	22.85/sqm	2536.35
	paint				

TOTAL RS. 45493.55



(A Subsidiary of Coal India Limited)

Bhuli Town Administration

Bhuli : Dhanbad- 828104 PHONE NO. 0326-2340420, 2340341

BILL OF QUANTITY FOR THE WORK OF BURIAL PIT IN R.H.BHULI FOR BIO MEDICAL WASTE MANAGEMENT. SL.NO. 2

SL. NO.	NAME OF ITEM	QTY	UNIT	RATE RS.	AMOUNT RS.
1.	Earth work in excavation in foundation by manual ordinary rock.	15.00 cum	Cum	162.65/cum	2439.75
2.	P.C.C. (1:4:8) in foundation.	0.6 cum	Cum	2449.00/cum	1469.40
3.	Brick work (1:6) in F & P of bricks C.D. 50	4.82 cum	Cum	2007.00/cum	9673.74
4.	12mm th. Plastering 1:6comp.job	21.60 sqm	Sqm	67.65/cum	1461.24
5.	Colour washing two coat etc.	21.60 sqm	Sqm.	9.10/sqm.	196.56

TOTAL RS.15240.69



(A Subsidiary of Coal India Limited)

Bhuli Town Administration

Bhuli : Dhanbad- 828104 PHONE NO. 0326-2340420, 2340341

BILL OF QUANTITY FOR THE WORK OF REPAIR & MAINT. OF QTR.NO. C/92 & C/414 AT C BLOCK, BHULI. SL.NO.3

SL.NO	NAME OF ITEM	QTY.	UNIT	RATE RS.	AMOUNTRS.
1.	12MM TH. CEWMENT PLASTER (1:6)	87.66	Sqm.	67.65/sqm	5930.19
		sqm.			
2.	6mm th. Cement plaster in 1:3 in ceiling.	16.50	Sqm.	62.15/sqm	1025.47
		sqm.			
3.	25mm th. Cement concrete floor.	68.54	Sqm.	86.05/sqm,.	5897.86
		sqm.			
4.	Halr brick work (1:4) in F & P.	3.42	Sqm.	257.80/sqm.	881.67
		sqm.			
5.	12mm th. Cewment plaster (1:4) with punning.	14.56	Sqm.	97.90/sqm.	1427.38
		sqm			
6.	Grading of roof with cement concrete (1:2:4)	1.45 cum	Cum.	3314.95/cum	4806.67
7.	P/F 25mm th, factory made batton shutter.	2.23 sqm	Sqm.	1320.50/sqm.	2944.71
8.	P/F/F sal wood work in frame.	0.066	Cum	30511.90/cum	2013.78
		cum			
9.	White washing two coat on old surface.	314.00	Sqm	4.10/ sqm.	1287.40
		sqm			
10.	Painting with synthetic enamel paint.	70.00	Sqm.	22.85/sqm	1599.50
		sqm			

TOTAL RS. 27.814.63



(A Subsidiary of Coal India Limited)

Bhuli Town Administration

Bhuli : Dhanbad- 828104 PHONE NO. 0326-2340420, 2340341

BILL OF QUANTITY FOR THE WORK OF REPAIR & MAINTENANCE OF B/13 AT OLD B TYPE QTR. AT BHULI. SL.NO.4

SL.NO.	NAME OF ITEM	QTY.	UNIT	RATE RS.	AMOUNT RS.
1.	P/F/F/ 30MM TH. TH. FLUSH DOOR ETC. COMPLETE JOB.	10.22 sqm	Sqm.	1317.65/sqm	13466.38
2.	P/F/F Wash Basin.	One No.	Each	754.00 each	753.00
3.	P/F/F/ beveled edge mirror.	1 No.	Each	493.65 each	493.65
4.	P/F F/4 PROOF M.S. wire gauze.	4.97 sqm	Sqm	443.80/sqm	2205.68
5.	p/f/f KITCHEN SINK	1 No.	Each	1444.00	1444.00
6.	P/F/F/ bib cock & stop cock 15 mm d.	6 Nos.	Each	191.70	1150.20
7.	6 mm th. Cement plaster in ceiling	7.00 sqm	Sqm.	62.15/sqm	435.05
8.	Dry distemper two coat.	132.95sqm.	Sqm	12.35/sqm	1641.80
9.	Painting with synthetic enamel paint.	42.17 sqm.	Sqm.	22.85/sqm	963.58
10.	White washing two coat.	39.00 sqm	Sqm.	4.10/sqm	159.90

TOTAL RS .22713.24



(A Subsidiary of Coal India Limited)

Bhuli Town Administration

Bhuli : Dhanbad- 828104 PHONE NO. 0326-2340420, 2340341

BILL OF QUANTITY FOR THE WORK OF REPAIR & MAINTENANCE OF C/1 C TYPE QTR. AT BHULI. SL.NO.5

SL.NO.	NAME OF TIEM	QTY.	UNIT	RATE RS.	AMOUNT RS.
1,	Distemper with oil bound distemper.	126.78 sqm	Sqm	14.90/sqm	1889.02
2.	White washing two coat.	240.07 sqm	Sqm.	4.10/sqm	984.28
3.	Painting with synthetic enamel paint.	63.95 sqm	Sqm.	22.85/sqm	1461.25
4.	Removing oil bound distemper.	126.78 sqm	Sqm	4.25/sqm	538.81
5.	Removing white washing.	240.07 sqm	Sqm	3.20/sqm	768.22
6.	12mm th. Cement plaster 1:6	30.00 sqm	Sqm.	67.65/sqm	2029.50
7.	6mm th. Cement plaster (1:3) in ceiling.	15.00 sqm	Sqm	62.15/sqm	932.25
8.	12mm th. Plaster (1:4) with neat cement punning.	5.00 sqm	Sqm.	97.90/sqm	489.50

TOTAL RS. 9092.83



(A Subsidiary of Coal India Limited)

Bhuli Town Administration

Bhuli : Dhanbad- 828104 PHONE NO. 0326-2340420, 2340341

BILL OF QUANTITY FOR THE WORK OF REPAIR & MAINT. OF BUNGLOW NO.2 NEAR R.H.BHULI. SL.NO.6

SL.NO.	NAME OF ITEM	QTY.	UNIT	RATE RS.	AMOUNT.RS.
1.	GRADING OF ROOF WITH	1.00 CUM.	CUM.	3314.95/CUM	3314.95
	CEMENT CONCRETE.				
2.	12MM TH. CEMENT PLASTER	118.38 SQM.	SQM.	67.65/SQM	8008.40
	(1:6) ON WALL.				
3.	12MM TH. PLASTER WITH	19.68 SQM.	SQM.	97.90/SQM.	1926.67
	PUNNING.				
4.	Dismentling old plaster etc.	110.44 sqm	Sqm.	8.20/sqm	905.60
5.	White washing two coat on old	668.26 sqm	Sqm	4.10/sqm	2739.86
	surface.				
6,.	Oil bound distemper two coat	133.11 sqm	Sqm.	13.85/sqm	1843.57
	on old suface existing wall.				
7.	Painting with synthetic enamel	145.47 sqm	Sqm.	22.85/sqm	3323.98
	paint.				

TOTAL RS.22063.03